

Corrections

Federal Register
Vol. 65, No. 215
Monday, November 6, 2000

This section of the FEDERAL REGISTER contains editorial corrections of previously published Presidential, Rule, Proposed Rule, and Notice documents. These corrections are prepared by the Office of the Federal Register. Agency prepared corrections are issued as signed documents and appear in the appropriate document categories elsewhere in the issue.

FEDERAL TRADE COMMISSION

Agency Information Collection Activities; Submission for OMB Review; Comment Request

Correction

In notice document 00–27158 beginning on page 63251 in the issue of Monday, October 23, 2000, make the following corrections:

1. On page 63252, in the first column, under the heading “**Burden Statement**” in the second paragraph, in the 19th line, “come burden” should read “some burden”.

2. On the same page, in the second column, under the heading “Non-Liquid Alternative Fuels”, in the sixth line, “5/

6 + 133 hours” should read “5/6 = 133 hours”.

[FR Doc. C0–27158 Filed 11–3–00; 8:45 am]
BILLING CODE 1505–01–D

GENERAL SERVICES ADMINISTRATION

41 CFR Part 101–2

[FPMR Amendment A–56]

RIN 3090–AH32

Payments to GSA for Supplies and Services Furnished Government Agencies

Correction

In rule document 00–27653 on page 64372 in the issue of Friday, October 27, 2000, make the following correction:

On page 64372, in the second column, under the heading “**PART 101–2–[REMOVED]**”, in the third line “496(c)” should read “486(c)”.

[FR Doc. C0–27653 Filed 11–3–00; 8:45 am]
BILLING CODE 1505–01–D

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98–ANE–47–AD; Amendment 39–11511; AD 2000–01–13]

RIN 2120–AA64

Airworthiness Directives; Pratt & Whitney JT9D Series Turbofan Engines

Correction

In rule document 00–1193, beginning on page 2864, in the issue of Wednesday, January 19, 2000, make the following corrections:

§39.13 [Corrected]

1. On page 2864, in the third column, in the sixth line from the bottom, remove the word “should”.

2. On page 2865, the table is corrected to read as follows:

Engine Model	Part	Engine Manual Part Number	FPI per Manual Section	Inspection
	Nomenclature			
7/7A/7AH/7F, 7H/7J/20/20J	All Fan Hubs	646028 (or the equivalent customized versions, 770407 and 770408).	72–31–04	02
7/7A/7AH/7F, 7H/7J/20/20J	All HPT 1st Disks	646028 (or the equivalent customized versions, 770407 and 770408).	72–51–02	01
7/7A/7AH/7F, 7H/7J/20/20J	All HPT 2nd Disks	646028 (or the equivalent customized versions, 770407 and 770408).	72–51–02	03
59A/70A	All Fan Hubs	754459	72–31–00	Heavy Maintenance Check
59A/70A	All HPT 1st Disks	754459	72–51–02	Heavy Maintenance Check
59A/70A	All HPT 2nd Disks	754459	72–51–02	Heavy Maintenance Check
7Q/7Q3	All Fan Hubs	777210	72–31–00	03
7Q/7Q3	All HPT 1st Disks	777210	72–51–06	01
7Q/7Q3	All HPT 2nd Disks	777210	72–51–07	01
7R4	All Fan Hubs	785058, 785059 and 789328	72–31–00	03
7R4	All HPT 1st Disks	785058, 785059 and 789328	72–51–06	01
7R4	All HPT 2nd Disks	785058, 785059 and 789328	72–51–07	01

[FR Doc. C0–1193 Filed 11–3–00; 8:45 am]
BILLING CODE 1505–01–D